

4

We are missing the boat in Akron by not leaving a fly store
(April 4, 1909) - C.E.H.

Mounts -

58 St. Joseph, Mo.

Okad.

John The development - ^(D&T) Expect to file for their license next wk.
upto date - ?

Doc. No. 2. C. L. J. P. W.
J. H. W. H. J. L. J. P. W. R. L. B.
R. B. W. J. L. J. P. W. R. L. B.
R. H. W. J. L. J. P. W. R. L. B.
R. J. V. C. B. J. P. W.

#5035 *Pegina* *lask.* - a must. - 70'8" x 200'

Add 5 ft. edging (cut 32m), take off 3 ft.

Build new addition to rear. - ^{included} cost 443.14.

(2) Walter R. Adams

5005 = Wanders, Mon

Cont. exp #24M.

Add. space - new front, new fixtures, new flr, air cond.

Newspace - H16'

~~Old - 885~~

Gain - 232'

air conditioning said to be necessary (N.H.) (it rained ?);

Other stores are air cond., but not D.W.

So. fln as is, do not air cond., new front

Do not do big job. - Resurvey + refigure.

5072 - Weston, Ont (nr. Toronto) 75' x 130'

New location, new bldg. - cost 3934. (cont)

Follow up is - (2)
Est. sales 5000 P. P. 100000 H. 100000

Calc. for 38 M ; $\text{Kc B} + \text{C.E.H}_2$ then $\text{K} 400\text{ M}$ is more realistic
a $\text{Kc F} - 51\text{ M}$.

100. Store, 32 - 100 ft

